Release Note for Vigor2927 Series

Firmware Version:	4.5.1.1
Release Type:	Critical – Upgrade immediately to address urgent security issues or major system risks
Applied Models:	Vigor2927, Vigor2927ac, Vigor2927Vac, Vigor2927L, Vigor2927Lac, Vigor2927ax, Vigor2927F, Vigor2927L-5G, Vigor2927Lax-5G

Vigor2927 series is a broadband router which integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth. The state-of-art routing feature, VPN security, and Dual-WAN provide integrated benefits for professional users and small offices.

New Features

- None.

Improvement

- Improved: Improve the WiFi Driver Security (CVE-2025-20710, CVE-2025-20715, CVE-2025-20716, CVE-2025-20718, CVE-2025-20719, CVE-2025-20720, CVE-2025-20724, CVE-2025-20733, CVE-2025-20734, CVE-2025-20736, CVE-2025-20737, CVE-2025-20738 and CVE-2025-20739).

- Corrected: An issue with the device losing connection due to unstable LTE.

- Corrected: An issue with the failure to log in to the web user interface for multi-language support.

Known Issue

- None.

Note

- IPsec HMAC (MD5) is no longer supported.