

Release Note for VigorAP 1000C

Firmware Version:	1.4.4
Release Type:	Normal
Applied Models:	VigorAP 1000C

VigorAP 1000C is a ceiling-mount Wi-Fi for business networks. As a tri-band AP, it provides an extra 5GHz Wireless band which increases the supported number of wireless devices. In Mesh mode or Range Extender mode, this extra band can also be dedicated as the Uplink band to the Internet. VigorAP 1000C is suitable to construct a small Wireless network.

New Features

- None.

Improvement

- Improved: Improve the DNS security (CVE-2022-30295).
- Improved: Support Allow management from WLAN (System Maintenance >> Management).
- Corrected: An issue of Mesh network connection when Mesh Root is Vigor2862 or Vigor2926.
- Corrected: An issue of APM failure on the Vigor router when upgrading the firmware of VigorAP from 1.4.2 to 1.4.3

Known Issue

- System performance will drop when Bonding is enabled.

Note

- The throughput figures are maximum, based on DrayTek internal testing with optimal conditions. The actual performance may vary depending on the different network conditions and applications activated.