

Release Note for Vigor2133 Series

Firmware Version:	3.9.9.6
Release Type:	Critical – Upgrade immediately to address urgent security issues or major system risks
Applied Models:	Vigor2133 / Vigor2133n / Vigor2133ac / Vigor2133Vac / Vigor2133FVac

Vigor2133 features advanced bandwidth control mechanism such as IP-layer, QoS, NAT Session Limitation, Bandwidth Borrowed, etc., to allow easy, flexible, reliable access control and bandwidth management.

New Features

- None.

Improvement

- Improved: Enhance SQLite 3.9.2 security by applying patches to address multiple known security issues, including CVE-2018-20346, CVE-2018-20505, CVE-2018-20506, CVE-2018-8740, CVE-2019-16168, CVE-2019-19645, CVE-2019-19646, CVE-2019-8457, CVE-2020-11655, CVE-2020-11656, CVE-2020-13434, CVE-2020-13435, CVE-2020-13630, CVE-2020-13631, CVE-2020-13632, CVE-2020-15358, CVE-2022-35737, CVE-2023-7104, CVE-2025-3277, and CVE-2025-6965.
- Corrected: An issue where certain VoIP/SIP attacks could cause the router to reboot unexpectedly.
- Corrected: An issue where the router could reboot unexpectedly under certain VoIP/SIP conditions.

Known Issue

- None.