

Release Note for Vigor3910 Series

Firmware Version:	3.9.2
Release Type:	Normal
Applied Models:	Vigor3910

New Features

- Support VPN Matcher Setup.
- Support interchangeable LAN/WAN.
- Support (SWM) switch management for Vigor switch, up to 30 devices.
- Support (APM) AP management for Vigor access point, up to 50 devices.

Improvement

- Improved: Increase DHCP pool from 1021 up to 4K.
- Improved: Support PPTP acceleration up to 320Mbps.
- Improved: Support SSL VPN acceleration up to 1.6Gbps.
- Improved: Support VPN trunk (GRE over IPsec) acceleration.
- Improved: Support LAN port mirror and WUI packet capture.
- Improved: Support APP QoS for bandwidth management.
- Improved: Support console menu under LAN.

Known Issue

- Once upgraded to 3.9.2, configure IP Bind MAC settings and then get downgraded to 3.9.1 again. The IP Bind MAC settings will disappear. So make sure the IP Bind MAC settings is backed up before downgrading.

Note

The following items will be ready in the future release:

- USB Applications
- Central Management
- WAN >> Multi-VLAN >> Port-based bridge
- Bandwidth Management >> APP QoS / VoIP QoS

The following traffic will be accelerated (in the fast path) in the future release

- All IPv6 traffic
- Non-IPsec VPN traffic (e.g. PPTP, SSL)
- VigorACS server will be fully compatible with this router